

SAS Superstructure

Location: 04-SF-80-13.2 / 13.9 Client Name: CalTrans **Run date** 21-Nov-14 **Time** 12:44 AM

04-0120F4

04-SF-80-13.2/13.9

Self-Anchored

Suspension Bridge

Daily Diary Report by Bid Item

Contract No.: 04-0120F4

Diary #: 125 Const Calendar Day: 618 Date: 19-May-2011 Thursday Inspector Name: Khow, Sanny Title: Transportation Engineer

Inspection Type: Continuous

Shift Hours: 07:00 AM 17:30 PM **Break:** 00:30 **Over Time:** 02:00

Federal ID: Location:

Reviewer: Soheilifard, Saman Approved Date: 25-Jul-11 Status: Approved

Weather

Temperature 7 AM 12 PM 4PM Precipitation Condition

Working Day **V** If no, explain:

04-0120F4 Bid Item: 053 T-L01-SFN.053 Tower Lift 01 Strut Façades North Erect structural steel (bridge tower)

AMERICAN BRIDGE/FLUOR, A JV

04-0120F4 Bid Item: 053 T-L01-TNE.053 Tower Lift 01 Tower NE Erect structural steel (bridge tower)

AMERICAN BRIDGE/FLUOR, A JV

04-0120F4 Bid Item: 053 T-L04-BNW.053 Tower Lift 04 Bolt Tower NW

AMERICAN BRIDGE/FLUOR, A JV

	Labor								
	Trade	Class	Name	RT Hrs	OT Hrs	DT Hrs	Total	Remarks	Dispute
l	Contractor:	AMERICAN BRIDGE/F	LUOR, A JV						
	Ironworker	APP	LUIS PLANCARTE	8.00	2.00	0.00	10.00		
	Ironworker	APP	Lorenzo Padilla	8.00	2.00	0.00	10.00		
	Ironworker	JNM	EDUARDO JIMENEZ-PADILLA	8.00	2.00	0.00	10.00		
l	Ironworker	JNM	Wei Tan	8.00	2.00	0.00	10.00		
	Ironworker	JNM	MATTHEW GREER	8.00	2.00	0.00	10.00		
	Ironworker	FOR	Kevin Karnar	8.00	2.00	0.00	10.00		

Diary: Dispute

General Comments 053 T-L04-BNW.053

Attend safety meeting at the SAS office.

Final Bolt Field Splice 3

North Shaft

Tan, Lorenzo and Eddy tension bolts on the upper half of longitudinal stiffener splice plate at A1, A2, A3, and A4.

Tan, Lorenzo and Eddy tension bolts on the upper half of longitudinal stiffener splice plate at E1, and E2.

Luiz and Matt tension bolts from the heads on the skin plates.



Page 1 of 2

Daily Diary Report by Bid Item

Inspector Name: Khow, Sanny Job Name: 04-0120F4 Diary #: 125 Date: 19-May-2011

Matt tensions on the outside of the shaft from the bolt heads while Luis is holding the nuts from the inside. They are tensioning on the skin C, skin D and skin E.

and Eddy tansian halts an the upper half of skin plates from inside (from the nut side) for all

04-0120F4	Bid Item: 078	T-L02-ISW.078	Tower Lift 02 Internal Paint Tower SW	
ERTIFIED CO	ATINGS COMPANY			
_abor				
Trade	Class	Name	RT Hrs OT Hrs DT Hrs Total Remarks	Dispute
Contractor:	CERTIFIED COATING	S COMPANY		
Painter	FOR	MIKE GAYA	0.00 0.00 0.00 0.00	
Painter	FOR	TONY KATRONES	0.00 0.00 0.00 0.00	
04-0120F4	Bid Item: 078	T-L02-ISW.078	Tower Lift 02 Internal Paint Tower SW	
	IDGE/FLUOR, A JV	. 202 10111010		

